

Contact

Post: REPUBLIC OF SINGAPORE
AERONAUTICAL INFORMATION SERVICES
Civil Aviation Authority of Singapore
60 Airport Boulevard,
Changi Airport Terminal 2, #04-01
Singapore 819643

Tel: (65) 6955 0400
Fax: (65) 6441 0221
AFS: WSSSYNYX
Email: caas_singaporeais@caas.gov.sg
URL: <https://www.caas.gov.sg>
URL: <https://aim-sg.caas.gov.sg>

**AIP Supplement for
Singapore****AIRAC AIP SUP
097/2026**

Effective from
06 AUG 2026

to
30 SEP 2026

Published on
25 JUN 2026

**SINGAPORE CHANGI AIRPORT – TEMPORARY DEACTIVATION OF RAPID EXIT TAXIWAY
INDICATOR LIGHTS (RETIL) AT RUNWAY 02C/20C, SINGAPORE CHANGI AIRPORT****1 INTRODUCTION**

1.1 This AIRAC AIP Supplement is to inform airline operators and pilots of the continued temporary deactivation of Rapid Exit Taxiway Indicator Lights (RETILs) at Runway 02C and 20C in Singapore Changi Airport.

1.2 This deactivation period is from **06 August 2026, 0901UTC until 30 September 2026, 0900UTC**.

1.3 This initiative forms part of an operational evaluation and optimisation exercise, undertaken to assess system effectiveness, operational reliance, and alignment with current aircraft and runway performance.

2 TEMPORARY DEACTIVATION OF LIGHTING

2.1 As part of this structured evaluation, all RETILs along Runway 02C and 20C have been deactivated and the circuits isolated for the duration of the trial period.

2.2 The assessment aims to validate:

- Continued safe and efficient runway operations in the absence of RETIL,
- Pilot situational awareness and exit performance using existing visual aids,
- Effectiveness and continued need for RETIL under current operating conditions and to support long-term planning.

2.3 A total of 66 RETIL units are affected. Please refer to **Annex A** for their locations on Runway 02C, and **Annex B** for locations on Runway 20C.

3 OPERATIONAL CONSIDERATIONS

3.1 Pilots are advised to continue operations using standard runway exit procedures, supported by:

- Published taxiway layouts and aerodrome charts,
- Taxiway centreline lighting and guidance systems,
- Aerodrome signage and surface markings,
- ATC instructions and surveillance support.

3.2 Changi Airport will continue to closely monitor operational performance and safety indicators throughout the trial period.

4 CHANGES


4.1 Any change to the contents of this AIRAC AIP Supplement will be notified through NOTAM.

Enlarged location plan of all Rapid Exit Taxiway Indicator Lights at Runway 02C - Annex A

Enlarged location plan of all Rapid Exit Taxiway Indicator Lights at Runway 20C - Annex B

Intentionally Left Blank

ENLARGED LOCATION PLAN OF RAPID EXIT TAXIWAY INDICATOR LIGHTS (RETIL) ON RUNWAY 02C, SINGAPORE CHANGI AIRPORT




Legend

 RWY 02C RETIL

Intentionally Left Blank

ENLARGED LOCATION PLAN OF RAPID EXIT TAXIWAY INDICATOR LIGHTS (RETIL) ON RUNWAY 20C, SINGAPORE CHANGI AIRPORT



Legend

 RWY 20C RETIL

Intentionally Left Blank