


AERODROME ADVISORY CHART



Advisory 4
Pilots taxiing on TWY V are to maintain a lookout to ensure sufficient wing tip clearance.

Advisory 1
Pilots taxiing on TWY C1 are to maintain a lookout to ensure sufficient wing tip clearance.

Advisory 2
Pilots taxiing on TWY EP are to maintain a lookout to ensure sufficient wing tip clearance.

Advisory 3
Pilots taxiing on TWY N or P to holding point EN or E1 via TWY EP are to pay extra attention to ground signages and lightings to prevent the mistaken identification of TWY EP as RWY 20C.