

Advisory 1

Pilots taxiing on TWY R4 are to maintain a lookout to ensure sufficient wing tip clearance.

Advisory 2

Pilots taxiing on TWY T are to maintain a lookout to ensure sufficient wing tip clearance.

Advisory 3

Pilots taxiing on TWY N or P to holding point T1 or T2 via TWY T are to pay extra attention to ground signage and lightings to prevent the mistaken identification of TWY T as RWY 20C.

Advisory 4

Pilots taxiing on TWY V are to maintain a lookout to ensure sufficient wing tip clearance.

AREA CLOSED FOR CHANGEBAST CONSTRUCTION WORKS (INCLUDING RUNWAY 02C/20C)